| | | | | | | | | | | Annual Probability | Consequence Data | | Risk Indexes | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| row number | Project Number | District | (7) Project Name | Project Center River Mile | Bank (L/R) | NLD System Number | NDL Segment Number | Failure Mode Addressed | Calculated OT Frequency | Annual Likelihood of Breach due to Failure Mode Addressed | LOL by Failure Mode | Adjusted LOL by Failure Mode | Risk Index | Adjusted Risk Index | Risk Rank | Item Catogory | Catagory Rank |
| 202 | 3150 | MVN | Dugas to Celotex | 100.4 | R | 4405000557 | 4404000558 | Overtopping | 8786 | 1.119E-04 | 322 | 354.2 | 3.60E+02 | 3.96E+02 | 91 | MR | 5 |
| 131 | 3305 | MVN | Plaquemine/Reveille | 206.7 | R | 4405000525 | 4404000534 | Slope/Bank Stability | 5924 | 8.293E-04 | 43.07 | 47.377 | 3.57E+02 | 3.93E+02 | 92 | RV | 9 |
| 137 | 3365 | MVN | Smoke Bend | 178 | R | 4405000525 | 4404000534 | Slope/Bank Stability | 5924 | 8.293E-04 | 43.07 | 47.377 | 3.57E+02 | 3.93E+02 | 92 | RV | 9 |
| 212 | 3450 | MVN | Waggaman | 110.4 | R | 4405000557 | 4404000558 | Overtopping | 8977 | 1.095E-04 | 322 | 354.2 | 3.53E+02 | 3.88E+02 | 94 | MR | 6 |
| 200 | 3055 | MVN | Barataria Blvd. | 99.5 | R | 4405000557 | 4404000558 | Overtopping | 9035 | 1.088E-04 | 322 | 354.2 | 3.50E+02 | 3.86E+02 | 95 | MR | 7 |
| 39 | 1440 | MVM | West Memphis, AR Seepage Remediation | 723 | L | 4005000002 | 4004000017 | Seepage | 500 | 1.673E-04 | 229 | 229 | 3.83E+02 | 3.83E+02 | 96 | PR | 69 |
| 7 | 1225 | MVM | Mound City to Cairo, IL 7/50+00 to 8/4+00 | 959 | R | 4005000001 | 4004000002 | Overtopping | 1000 | 9.706E-04 | 39 | 39 | 3.79E+02 | 3.79E+02 | 97 | PR | 70 |
| 197 | 3030 | MVN | Ama | 113.5 | R | 4405000557 | 4404000558 | Overtopping | 9240 | 1.064E-04 | 322 | 354.2 | 3.43E+02 | 3.77E+02 | 98 | MR | 8 |
| 201 | 3125 | MVN | Cyanamid | 115.5 | R | 4405000557 | 4404000558 | Overtopping | 9372 | 1.049E-04 | 322 | 354.2 | 3.38E+02 | 3.72E+02 | 99 | MR | 9 |
| 36 | 1300 | MVM | Poker Point, AR | 749 | R | 4005000002 | 4004000017 | Seepage | 500 | 1.593E-04 | 229 | 229 | 3.65E+02 | 3.65E+02 | 100 | PR | 71 |
| 242 | 2245 | MVK | Waterproof-Upperlake Concordia, La, Levees and | 368 | R | 5905000001 | 5904000024 | Overtopping | 2312 | 4.215E-04 | 77.32 | 85.052 | 3.26E+02 | 3.58E+02 | 101 | PR | 72 |
| 28 | 1090 | MVM | Butler, AR Item 782R | 728 | R | 4005000002 | 4004000017 | Seepage | 500 | 1.231E-04 | 229 | 229 | 2.82E+02 | 2.82E+02 | 102 | PR | 73 |
| 35 | 1190 | MVM | Huffman, AR | 828 | R | 4005000002 | 4004000017 | Seepage | 500 | 1.195E-04 | 229 | 229 | 2.74E+02 | 2.74E+02 | 103 | PR | 74 |
| 57 | 1240 | MVM | Modoc, AR | 643 | R | 4005000006 | 4004000020 | Seepage | 8500 | 2.046E-03 | 12 | 13.2 | 2.46E+02 | 2.70E+02 | 104 | PR | 75 |
| 232 | 2200 | MVK | St. Joseph-Waterproof, La, Levee and Berms, Iter | 385 | R | 5905000001 | 5904000024 | Overtopping | 3347 | 2.911E-04 | 77.32 | 85.052 | 2.25E+02 | 2.48E+02 | 105 | PR | 76 |
| 10 | 1450 | MVM | Cairo, IL Relief Wells Mississippi River Levee | 7M | L | 4005000001 | 4004000003 | Seepage | 300 | 1.598E-04 | 147 | 147 | 2.35E+02 | 2.35E+02 | 106 | PR | 77 |
| 24 | 1080 | MVM | Below New Madrid, MO (Parcel 2) | 885 | R | 4005000002 | 4004000015 | Seepage | 500 | 1.593E-04 | 141 | 141 | 2.25E+02 | 2.25E+02 | 107 | PR | 78 |
| 244 | 2250 | MVK | Waterproof-Upperlake Concordia, La, Levees and | 370 | R | 5905000001 | 5904000024 | Overtopping | 3879 | 2.512E-04 | 77.32 | 77.32 | 1.94E+02 | 1.94E+02 | 108 | PR | 79 |
| 246 | 2255 | MVK | Yucatan-Lake Bruin, La, Levees and Berms, Item 3 | 398 | R | 5905000001 | 5904000024 | Overtopping | 4285 | 2.274E-04 | 77.32 | 85.052 | 1.76E+02 | 1.93E+02 | 109 | PR | 80 |
| 63 | 1220 | MVM | Mellwood, AR | 628 | R | 4005000006 | 4004000021 | Seepage | 8500 | 1.245E-03 | 14 | 15.4 | 1.74E+02 | 1.92E+02 | 110 | PR | 81 |
| 12 | 1105 | MVM | Commerce to Birds Point Grade Deficiency | 29M | R | 4005000002 | 4004000007 | Overtopping | 3999 | 2.301E-04 | 79 | 79 | 1.82E+02 | 1.82E+02 | 111 | PR | 82 |
| 238 | 2230 | MVK | Upper Lake Concordia-Vidalia, La, Levees and Ber | 366 | R | 5905000001 | 5904000024 | Overtopping | 4634 | 2.103E-04 | 77.32 | 85.052 | 1.63E+02 | 1.79E+02 | 112 | PR | 83 |
| 25 | 1245 | MVM | New Madrid, MO to MO-AR Levee (2/0+00 to 2/3 | 882 | R | 4005000002 | 4004000015 | Overtopping | 3898 | 2.361E-04 | 74 | 74 | 1.75E+02 | 1.75E+02 | 113 | PR | 84 |
| 26 | 1255 | MVM | New Madrid, MO to MO-AR Levee (5/0+00 to 0/0 | 888 | R | 4005000002 | 4004000015 | Overtopping | 4000 | 2.301E-04 | 74 | 74 | 1.70E+02 | 1.70E+02 | 114 | PR | 85 |
| 67 | 1210 | MVM | Knowlton, AR Item 612R | 612 | R | 4005000006 | 4004000023 | Seepage | 8500 | 1.245E-03 | 13 | 13 | 1.62E+02 | 1.62E+02 | 115 | PR | 86 |
| 15 | 1085 | MVM | Commerce to Birds Point (21/0+00 to 22/35+00) | 24M | R | 4005000002 | 4004000008 | Overtopping | 4499 | 2.046E-04 | 79 | 79 | 1.62E+02 | 1.62E+02 | 116 | PR | 87 |
| 27 | 1265 | MVM | South Caruthersville, MO Item 843R | 843 | R | 4005000002 | 4004000015 | Seepage | 500 | 1.138E-04 | 141 | 141 | 1.61E+02 | 1.61E+02 | 117 | PR | 88 |
| 236 | 2210 | MVK | St. Joseph-Waterproof, La, Levee and Berms, Iter | 393 | R | 5905000001 | 5904000024 | Overtopping | 5166 | 1.886E-04 | 77.32 | 85.052 | 1.46E+02 | 1.60E+02 | 118 | PR | 89 |
| 222 | 2045 | MVK | Bayou Vidal-Elkridge, La, Levee and Berms, Item 4 | 416 | R | 5905000001 | 5904000024 | Overtopping | 5034 | 1.936E-04 | 77.32 | 77.32 | 1.50E+02 | 1.50E+02 | 119 | PR | 90 |
| 234 | 2205 | MVK | St. Joseph-Waterproof, La, Levee and Berms, Iter | 388 | R | 5905000001 | 5904000024 | Overtopping | 5108 | 1.908E-04 | 77.32 | 77.32 | 1.47E+02 | 1.47E+02 | 120 | PR | 91 |
| 58 | 1280 | MVM | Oldtown, AR | 654 | R | 4005000006 | 4004000020 | Seepage | 8500 | 8.925E-04 | 15 | 16.5 | 1.34E+02 | 1.47E+02 | 121 | PR | 92 |
| 62 | 1120 | MVM | Fair Landing, AR | 632 | R | 4005000006 | 4004000021 | Seepage | 8500 | 8.925E-04 | 14 | 15.4 | 1.25E+02 | 1.37E+02 | 122 | PR | 93 |
| 286 | 2106 | MVK | Leland-Vancluse, Levee and Berms, Item 536.0-R | 536 | R | 5905000001 | 5904000062 | Overtopping | 6347 | 1.535E-04 | 80.34 | 88.374 | 1.23E+02 | 1.36E+02 | 123 | PR | 94 |
| 250 | 2260 | MVK | Yucatan-Lake Bruin, La, Levees and Berms, Item 4 | 401 | R | 5905000001 | 5904000024 | Overtopping | 5567 | 1.750E-04 | 77.32 | 77.32 | 1.35E+02 | 1.35E+02 | 124 | PR | 95 |
| 59 | 1400 | MVM | Westover, AR | 653 | R | 4005000006 | 4004000020 | Seepage | 8500 | 8.925E-04 | 15 | 15 | 1.34E+02 | 1.34E+02 | 125 | PR | 96 |
| 224 | 2155 | MVK | Point Pleasant-Yucatan, La, Levee and Berms, Iter | 407 | R | 5905000001 | 5904000024 | Overtopping | 5673 | 1.718E-04 | 77.32 | 77.32 | 1.33E+02 | 1.33E+02 | 126 | PR | 97 |
| 309 | 1140 | MVM | Friars Point,MS | 646 | L | 5905000021 | 4004000026 | Seepage | 4876 | 1.031E-04 | 117 | 128.7 | 1.21E+02 | 1.33E+02 | 127 | PR | 98 |
| 34 | 1175 | MVM | MO-AR State Line to St. Francis River Levee (200/ | 689 | R | 4005000002 | 4004000017 | Overtopping | 5965 | 1.543E-04 | 86 | 86 | 1.33E+02 | 1.33E+02 | 128 | PR | 99 |
| 90 | 3255 | MVN | Montz Revetment | 132.5 | L | 4405000501 | 4404000502 | Slope/Bank Stability | 1738 | 7.471E-04 | 16 | 17.6 | 1.20E+02 | 1.31E+02 | 129 | RV | 11 |
| 271 | 2565 | MVK | Moreville-Black Hawk, La, Levee Enlargement, Ite | 351 | R | 5905000001 | 5904000024 | Overtopping | 5800 | 1.680E-04 | 77.32 | 77.32 | 1.30E+02 | 1.30E+02 | 130 | PR | 100 |
| 262 | 2530 | MVK | Moreville-Black Hawk, La, Seepage Control, Item | 337 | R | 5905000001 | 5904000024 | Seepage | 1400 | 8.523E-05 | 147.04 | 147.04 | 1.25E+02 | 1.25E+02 | 131 | UC | 9 |
| 226 | 2160 | MVK | Point Pleasant-Yucatan, La, Levee and Berms, Iter | 409 | R | 5905000001 | 5904000024 | Overtopping | 6100 | 1.597E-04 | 77.32 | 77.32 | 1.24E+02 | 1.24E+02 | 132 | PR | 101 |
| 18 | 1330 | MVM | Samos, MO 946 R | 947 | R | 4005000002 | 4004000008 | Seepage | 500 | 1.535E-04 | 80 | 80 | 1.23E+02 | 1.23E+02 | 133 | PR | 102 |
| 22 | 1050 | MVM | Barnes Ridge, MO Item 910R | 914 | R | 4005000002 | 4004000010 | Seepage | 500 | 1.535E-04 | 80 | 80 | 1.23E+02 | 1.23E+02 | 133 | PR | 102 |
| 279 | 2020 | MVK | Above Lakeport-Harwood, Ark, Levee and Berms, | 528 | R | 5905000001 | 5904000062 | Overtopping | 6450 | 1.511E-04 | 80.34 | 80.34 | 1.21E+02 | 1.21E+02 | 135 | PR | 104 |

| | | | | | | | | | | Annual Probability | Consequence Data | | Risk Indexes | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| row number | Project Number | District | (7) Project Name | Project Center River Mile | Bank (L/R) | NLD System Number | NDL Segment Number | Failure Mode Addressed | Calculated OT Frequency | Annual Likelihood of Breach due to Failure Mode Addressed | LOL by Failure Mode | Adjusted LOL by Failure Mode | Risk Index | Adjusted Risk Index | Risk Rank | Item Catogory | Catagory Rank |
| 308 | 1130 | MVM | Flower Lake, MS | 673 | L | 5905000021 | 4004000026 | Seepage | 4876 | 1.031E-04 | 117 | 117 | 1.21E+02 | 1.21E+02 | 136 | PR | 105 |
| 312 | 1360 | MVM | Stovall, MS | 638 | L | 5905000021 | 4004000026 | Seepage | 4876 | 1.031E-04 | 117 | 117 | 1.21E+02 | 1.21E+02 | 136 | PR | 105 |
| 220 | 2040 | MVK | Bayou Vidal-Elkridge, La, Levee and Berms, Item 4 | 414 | R | 5905000001 | 5904000024 | Overtopping | 6311 | 1.544E-04 | 77.32 | 77.32 | 1.19E+02 | 1.19E+02 | 138 | PR | 107 |
| 13 | 1065 | MVM | Commerce to Birds Point (18/0+00 to 18/10+00) | 28M | R | 4005000002 | 4004000008 | Overtopping | 6199 | 1.485E-04 | 79 | 79 | 1.17E+02 | 1.17E+02 | 139 | PR | 108 |
| 275 | 2010 | MVK | Above Lakeport-Harwood, Ark, Levee and Berms, | 520 | R | 5905000001 | 5904000062 | Overtopping | 6676 | 1.460E-04 | 80.34 | 80.34 | 1.17E+02 | 1.17E+02 | 140 | PR | 109 |
| 277 | 2015 | MVK | Above Lakeport-Harwood, Ark, Levee and Berms, | 525 | R | 5905000001 | 5904000062 | Overtopping | 6691 | 1.456E-04 | 80.34 | 80.34 | 1.17E+02 | 1.17E+02 | 141 | PR | 110 |
| 91 | 3270 | MVN | New River Bend | 188 | L | 4405000501 | 4404000502 | Slope/Bank Stability | 1738 | 6.644E-04 | 16 | 17.6 | 1.06E+02 | 1.17E+02 | 142 | RV | 12 |
| 96 | 3380 | MVN | St. Elmo Revetment | 174.5 | L | 4405000501 | 4404000502 | Slope/Bank Stability | 1738 | 6.644E-04 | 16 | 17.6 | 1.06E+02 | 1.17E+02 | 142 | RV | 12 |
| 228 | 2165 | MVK | Point Pleasant-Yucatan, La, Levee and Berms, Iter | 411 | R | 5905000001 | 5904000024 | Overtopping | 7428 | 1.312E-04 | 80.3 | 88.33 | 1.05E+02 | 1.16E+02 | 144 | PR | 111 |
| 319 | 2060 | MVK | Brunswick-Halpino, Ms, Levee and Berms, Item 4 | 452 | L | 5905000021 | 5904000034 | Overtopping | 4876 | 2.009E-04 | 57.57 | 57.57 | 1.16E+02 | 1.16E+02 | 145 | PR | 112 |
| 327 | 2100 | MVK | James-Longwood, Ms, Levee and Berms, Item 52 | 521 | L | 5905000021 | 5904000034 | Overtopping | 4895 | 2.002E-04 | 57.57 | 57.57 | 1.15E+02 | 1.15E+02 | 146 | PR | 113 |
| 30 | 1145 | MVM | MO-AR State Line to St. Francis River Levee (145/ | 741 | R | 4005000002 | 4004000017 | Overtopping | 7000 | 1.315E-04 | 86 | 86 | 1.13E+02 | 1.13E+02 | 147 | PR | 114 |
| 31 | 1155 | MVM | MO-AR State Line to St. Francis River Levee (187/ | 697 | R | 4005000002 | 4004000017 | Overtopping | 7000 | 1.315E-04 | 86 | 86 | 1.13E+02 | 1.13E+02 | 147 | PR | 114 |
| 32 | 1165 | MVM | MO-AR State Line to St. Francis River Levee (190/ | 696 | R | 4005000002 | 4004000017 | Overtopping | 7092 | 1.298E-04 | 86 | 86 | 1.12E+02 | 1.12E+02 | 149 | PR | 116 |
| 267 | 2545 | MVK | Moreville-Black Hawk, La, Levee Enlargement, Ite | 345 | R | 5905000001 | 5904000024 | Overtopping | 6785 | 1.436E-04 | 77.32 | 77.32 | 1.11E+02 | 1.11E+02 | 150 | PR | 117 |
| 288 | 2110 | MVK | Luna-Leland, Ar, Levee and Berm, Item 541-R | 541 | R | 5905000001 | 5904000062 | Overtopping | 7804 | 1.249E-04 | 80.3 | 88.33 | 1.00E+02 | 1.10E+02 | 151 | PR | 118 |
| 253 | 2500 | MVK | Moreville-Black Hawk, La, Levee Enlargement, Ite | 320 | R | 5905000001 | 5904000024 | Overtopping | 7127 | 1.367E-04 | 77.32 | 77.32 | 1.06E+02 | 1.06E+02 | 152 | PR | 119 |
| 270 | 2560 | MVK | Moreville-Black Hawk, La, Levee Enlargement, Ite | 349 | R | 5905000001 | 5904000024 | Overtopping | 7127 | 1.367E-04 | 77.32 | 77.32 | 1.06E+02 | 1.06E+02 | 152 | PR | 119 |
| 281 | 2050 | MVK | Below Arkansas City, Ar, Levee and Berms, Item 5 | 555 | R | 5905000001 | 5904000062 | Overtopping | 8400 | 1.160E-04 | 80.3 | 88.33 | 9.32E+03 | 1.02E+02 | 154 | MR | 10 |
| 269 | 2555 | MVK | Moreville-Black Hawk, La, Levee Enlargement, Ite | 348 | R | 5905000001 | 5904000024 | Overtopping | 7479 | 1.303E-04 | 77.32 | 77.32 | 1.01E+02 | 1.01E+02 | 155 | PR | 121 |
| 321 | 2065 | MVK | Brunswick-Halpino, Ms, Levee and Berms, Item 4 | 458 | L | 5905000021 | 5904000034 | Overtopping | 5621 | 1.743E-04 | 57.57 | 57.57 | 1.00E+02 | 1.00E+02 | 156 | PR | 122 |
| 256 | 2510 | MVK | Moreville-Black Hawk, La, Levee Enlargement, Ite | 328 | R | 5905000001 | 5904000024 | Overtopping | 7804 | 1.249E-04 | 77.32 | 77.32 | 9.65E+03 | 9.65E+03 | 157 | PR | 123 |
| 248 | 2256 | MVK | Yucatan-Lake Bruin, La, Levees and Berms, Item 3 | 398 | R | 5905000001 | 5904000024 | Overtopping | 9040 | 1.078E-04 | 80.3 | 88.33 | 8.66E+03 | 9.52E+03 | 158 | MR | 11 |
| 210 | 3275 | MVN | Nine Mile Point - Landside shift | 105.5 | R | 4405000557 | 4404000558 | Slope/Bank Stability | 4558 | 2.770E-03 | 322 | 354.2 | 8.92E+01 | 9.81E+01 | 10 | PR | 9 |
| 198 | 3045 | MVN | Avondale Revetment (Awarded) | 108.5 | R | 4405000557 | 4404000558 | Slope/Bank Stability | 4558 | 2.770E-03 | 322 | 354.2 | 8.92E+01 | 9.81E+01 | 10 | RV | 2 |
| 175 | 3600 | MVN | Spanish Plaza | 95 | L | 4405000556 | 4404000505 | Floodwall Stability | 2014 | 2.002E-04 | 4121 | 4533.1 | 8.25E+01 | 9.07E+01 | 12 | PR | 10 |
| 161 | 3225 | MVN | Kenner Bend Revetment | 115 | L | 4405000556 | 4404000503 | Slope/Bank Stability | 2014 | 7.470E-04 | 974 | 1071.4 | 7.28E+01 | 8.00E+01 | 13 | RV | 3 |
| 9 | 1035 | MVM | Cairo, IL Floodwall | 957 | R | 4005000001 | 4004000003 | Floodwall Stability | 300 | 5.379E-03 | 147 | 147 | 7.91E+01 | 7.91E+01 | 14 | PR | 11 |
| 307 | 1110 | MVM | Commerce, MS | 698 | L | 5905000021 | 4004000026 | Seepage | 4876 | 4.829E-03 | 117 | 117 | 5.65E+01 | 5.65E+01 | 15 | PR | 12 |
| 310 | 1270 | MVM | Norfolk, MS | 712 | L | 5905000021 | 4004000026 | Seepage | 4876 | 4.829E-03 | 117 | 117 | 5.65E+01 | 5.65E+01 | 15 | PR | 12 |
| 164 | 3210 | MVN | INHC Lock - Structure | 93 | L | 4405000556 | 4404000505 | Overtopping | 2014 | 4.883E-04 | 974 | 1071.4 | 4.76E+01 | 5.23E+01 | 17 | LK | 1 |
| 33 | 1170 | MVM | Horseshoe Lake, AR | 705 | R | 4005000002 | 4004000017 | Seepage | 500 | 2.054E-03 | 229 | 229 | 4.70E+01 | 4.70E+01 | 18 | PR | 14 |
| 4 | 1430 | MVM | North Mound City, IL Sump | 961 | R | 4005000001 | 4004000001 | Seepage | 300 | 7.406E-03 | 51 | 51 | 3.78E+01 | 3.78E+01 | 19 | PR | 15 |
| 221 | 2040 | MVK | Bayou Vidal-Elkridge, La, Levee and Berms, Item 4 | 414 | R | 5905000001 | 5904000024 | Seepage | 1400 | 2.567E-03 | 147.04 | 147.04 | 3.77E+01 | 3.77E+01 | 20 | PR | 16 |
| 172 | 3585 | MVN | Item M-100-L; NASHVILLE AVE. TO NAPOLEON AV | 100 | L | 4405000556 | 4404000505 | Floodwall Stability | 2014 | 8.067E-05 | 4121 | 4533.1 | 3.32E+01 | 3.66E+01 | 21 | UC | 1 |
| 233 | 2200 | MVK | St. Joseph-Waterproof, La, Levee and Berms, Iten | 385 | R | 5905000001 | 5904000024 | Seepage | 1400 | 2.190E-03 | 147.04 | 161.744 | 3.22E+01 | 3.54E+01 | 22 | PR | 17 |
| 203 | 3150 | MVN | Dugas to Celotex | 100.4 | R | 4405000557 | 4404000558 | Seepage | 4558 | 4.091E-04 | 750 | 825 | 3.07E+01 | 3.37E+01 | 23 | PR | 18 |
| 209 | 3275 | MVN | Nine Mile Point (Awarded) | 105.5 | R | 4405000557 | 4404000558 | Seepage | 4558 | 4.091E-04 | 750 | 825 | 3.07E+01 | 3.37E+01 | 23 | PR | 18 |
| 278 | 2015 | MVK | Above Lakeport-Harwood, Ark, Levee and Berms, | 525 | R | 5905000001 | 5904000062 | Seepage | 1400 | 2.190E-03 | 152.79 | 152.79 | 3.35E+01 | 3.35E+01 | 25 | PR | 20 |
| 280 | 2020 | MVK | Above Lakeport-Harwood, Ark, Levee and Berms, | 528 | R | 5905000001 | 5904000062 | Seepage | 1400 | 2.190E-03 | 152.79 | 152.79 | 3.35E+01 | 3.35E+01 | 25 | PR | 20 |
| 247 | 2255 | MVK | Yucatan-Lake Bruin, La, Levees and Berms, Item 3 | 398 | R | 5905000001 | 5904000024 | Seepage | 1400 | 2.028E-03 | 147.04 | 161.744 | 2.98E+01 | 3.28E+01 | 27 | PR | 22 |
| 160 | 3135 | MVN | Destrahan Revetment | 120 | L | 4405000556 | 4404000503 | Slope/Bank Stability | 2014 | 2.996E-04 | 974 | 1071.4 | 2.92E+01 | 3.21E+01 | 28 | RV | 4 |
| 166 | 3265 | MVN | New Orleans District (Awarded) | 102.7 | L | 4405000556 | 4404000505 | Overtopping | 3755 | 2.619E-04 | 974 | 1071.4 | 2.55E+01 | 2.81E+01 | 29 | PR | 23 |
| 276 | 2010 | MVK | Above Lakeport-Harwood, Ark, Levee and Berms, | 520 | R | 5905000001 | 5904000062 | Seepage | 1400 | 1.574E-03 | 152.79 | 152.79 | 2.41E+01 | 2.41E+01 | 30 | PR | 24 |
| 235 | 2205 | MVK | St. Joseph-Waterproof, La, Levee and Berms, Iten | 388 | R | 5905000001 | 5904000024 | Seepage | 1400 | 1.574E-03 | 147.04 | 147.04 | 2.31E+01 | 2.31E+01 | 31 | PR | 25 |

| | | | | | | | | | | Annual Probability | Consequence Data | | Risk Indexes | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| row number | Project Number | District | (7) Project Name | Project Center River Mile | Bank (L/R) | NLD System Number | NDL Segment Number | Failure Mode Addressed | Calculated OT Frequency | Annual Likelihood of Breach due to Failure Mode Addressed | LOL by Failure Mode | Adjusted LOL by Failure Mode | Risk Index | Adjusted Risk Index | Risk Rank | Item Catogory | Catagory Rank |
| 23 | 1055 | MVM | Caruthersville, MO Floodwall | 846 | R | 4005000002 | 4004000015 | Overtopping | 8953 | 1.028E-04 | 74 | 74 | 7.61E+03 | 7.61E+03 | 181 | MR | 20 |
| 295 | 2305 | MVK | Catfish Point, Ark, Seepage Control, Item 571+R | 571 | R | 5905000001 | 5904000062 | Seepage | 1400 | 4.924E-05 | 152.8 | 152.8 | 7.52E+03 | 7.52E+03 | 182 | UC | 18 |
| 300 | 2330 | MVK | Yellow Bend Harbor, Ark, Seepage Control, Item 5 | 553 | R | 5905000001 | 5904000062 | Seepage | 1400 | 4.924E-05 | 152.8 | 152.8 | 7.52E+03 | 7.52E+03 | 182 | UC | 18 |
| 302 | 2340 | MVK | Ashbrook Island, Ark, Seepage Control, Item 549+ | 549 | R | 5905000001 | 5904000062 | Seepage | 1400 | 4.924E-05 | 152.8 | 152.8 | 7.52E+03 | 7.52E+03 | 182 | UC | 18 |
| 303 | 2345 | MVK | Island 82, Ark, Seepage Control, Item 545+R | 545 | R | 5905000001 | 5904000062 | Seepage | 1400 | 4.924E-05 | 152.8 | 152.8 | 7.52E+03 | 7.52E+03 | 182 | UC | 18 |
| 335 | 2275 | MVK | Yazoo Cutoff, Ms, Levee and Berms, 443+L | 443 | L | 5905000021 | 5904000034 | Overtopping | 7589 | 1.291E-04 | 57.57 | 57.57 | 7.43E+03 | 7.43E+03 | 186 | PR | 130 |
| 6 | 1206 | MVM | Mound City to Cairo, IL 5/7+00 to 5/15+00 (Levee | 957 | R | 4005000001 | 4004000002 | Overtopping | 5909 | 1.643E-04 | 45 | 45 | 7.39E+03 | 7.39E+03 | 187 | PR | 131 |
| 1 | 1185 | MVM | Mound City to Cairo Levee 0/0+00 to 2/26+00 (L | 962 | R | 4005000001 | 4004000000 | Overtopping | 5965 | 1.627E-04 | 45 | 45 | 7.32E+03 | 7.32E+03 | 188 | PR | 132 |
| 245 | 2250 | MVK | Waterproof+Upperlake Concordia, La, Levees and | 370 | R | 5905000001 | 5904000024 | Seepage | 1400 | 4.924E-05 | 147.04 | 147.04 | 7.24E+03 | 7.24E+03 | 189 | UC | 22 |
| 136 | 3365 | MVN | Smoke Bend | 178 | R | 4405000525 | 4404000534 | Overtopping | 6949 | 1.424E-04 | 43.07 | 47.377 | 6.13E+03 | 6.75E+03 | 190 | PR | 133 |
| 20 | 1015 | MVM | BPNM Levee Raise R+890 | 890 | R | 4005000002 | 4004000010 | Overtopping | 10878 | 8.460E-05 | 79 | 79 | 6.68E+03 | 6.68E+03 | 191 | MR | 21 |
| 21 | 1660 | MVM | Birds Point + New Madrid Setback (12/32+00 to 3 | 890 | R | 4005000002 | 4004000010 | Overtopping | 10878 | 8.460E-05 | 79 | 79 | 6.68E+03 | 6.68E+03 | 191 | MR | 21 |
| 130 | 3305 | MVN | Plaquemine/Reveille (Awarded) | 206.7 | R | 4405000525 | 4404000534 | Overtopping | 7362 | 1.344E-04 | 43.07 | 47.377 | 5.79E+03 | 6.37E+03 | 193 | PR | 134 |
| 3 | 1205 | MVM | Mound City to Cairo Levee 4/30+00 to 5/7+00 | 961 | R | 4005000001 | 4004000001 | Overtopping | 5949 | 1.631E-04 | 39 | 39 | 6.36E+03 | 6.36E+03 | 194 | PR | 135 |
| 126 | 3065 | MVN | Bayou Goula to Alhambra | 194.5 | R | 4405000525 | 4404000534 | Overtopping | 7450 | 1.328E-04 | 43.07 | 47.377 | 5.72E+03 | 6.29E+03 | 195 | PR | 136 |
| 132 | 3325 | MVN | Port Allen | 231 | R | 4405000525 | 4404000534 | Overtopping | 7452 | 1.328E-04 | 43.07 | 47.377 | 5.72E+03 | 6.29E+03 | 196 | PR | 137 |
| 138 | 3410 | MVN | Thomas Point | 240.3 | R | 4405000525 | 4404000534 | Overtopping | 6842 | 1.447E-04 | 43.07 | 43.07 | 6.23E+03 | 6.23E+03 | 197 | PR | 138 |
| 254 | 2510 | MVK | Morevill+Black Hawk, La, Seepage Control, Item | 326 | R | 5905000001 | 5904000024 | Seepage | 1400 | 4.138E-05 | 147.04 | 147.04 | 6.08E+03 | 6.08E+03 | 198 | UC | 23 |
| 259 | 2522 | MVK | Morevill+Black Hawk, La, Seepage Control, Item | 331 | R | 5905000001 | 5904000024 | Seepage | 1400 | 4.138E-05 | 147.04 | 147.04 | 6.08E+03 | 6.08E+03 | 198 | UC | 23 |
| 261 | 2525 | MVK | Morevill+Black Hawk, La, Seepage Control, Item | 333 | R | 5905000001 | 5904000024 | Seepage | 1400 | 4.138E-05 | 147.04 | 147.04 | 6.08E+03 | 6.08E+03 | 198 | UC | 23 |
| 356 | 2455 | MVK | LaGrange, Ms, Seepage Control, Item 539+L | 539 | L | 5905000021 | 5904000034 | Seepage | 4876 | 4.911E-05 | 109.48 | 120.428 | 5.38E+03 | 5.91E+03 | 201 | UC | 26 |
| 231 | 2195 | MVK | St. Joseph+Waterproof, La, Levee and Berms, Iten | 380 | R | 5905000001 | 5904000024 | Seepage | 1400 | 3.518E-05 | 152.8 | 168.08 | 5.37E+03 | 5.91E+03 | 202 | UC | 27 |
| 282 | 2050 | MVK | Below Arkansas City, Ar, Levee and Berms, Item 5 | 555 | R | 5905000001 | 5904000062 | Seepage | 1400 | 3.518E-05 | 152.8 | 168.08 | 5.37E+03 | 5.91E+03 | 202 | UC | 27 |
| 289 | 2110 | MVK | Luna+Leland, Ar, Levee and Berm, Item 541+R | 541 | R | 5905000001 | 5904000062 | Seepage | 1400 | 3.518E-05 | 152.8 | 168.08 | 5.37E+03 | 5.91E+03 | 202 | UC | 27 |
| 296 | 2310 | MVK | Cypress Bend, Ark, Seepage Control, Item 569+R | 569 | R | 5905000001 | 5904000062 | Seepage | 1400 | 3.518E-05 | 152.8 | 168.08 | 5.37E+03 | 5.91E+03 | 202 | UC | 27 |
| 298 | 2320 | MVK | Choctaw Bend, Ark,Seepage Control, Item 560+R | 560 | R | 5905000001 | 5904000062 | Seepage | 1400 | 3.518E-05 | 152.8 | 168.08 | 5.37E+03 | 5.91E+03 | 202 | UC | 27 |
| 299 | 2325 | MVK | Below Arkansa City, Ark, Seepage Control, Item 5 | 556 | R | 5905000001 | 5904000062 | Seepage | 1400 | 3.518E-05 | 152.8 | 168.08 | 5.37E+03 | 5.91E+03 | 202 | UC | 27 |
| 2 | 1186 | MVM | Mound City to Cairo Levee 2/26+00 to 4/0+00 | 961 | R | 4005000001 | 4004000001 | Overtopping | 6538 | 1.485E-04 | 39 | 39 | 5.79E+03 | 5.79E+03 | 208 | PR | 139 |
| 123 | 3010 | MVN | Addis | 223 | R | 4405000525 | 4404000534 | Overtopping | 8163 | 1.212E-04 | 43.07 | 47.377 | 5.22E+03 | 5.74E+03 | 209 | MR | 23 |
| 133 | 3330 | MVN | Port Allen Lock + Levee | 228 | R | 4405000525 | 4404000534 | Overtopping | 8163 | 1.212E-04 | 43.07 | 47.377 | 5.22E+03 | 5.74E+03 | 209 | MR | 23 |
| 135 | 3355 | MVN | Smithfield Levee Enlargement | 246 | R | 4405000525 | 4404000534 | Overtopping | 7711 | 1.284E-04 | 43.07 | 43.07 | 5.53E+03 | 5.53E+03 | 211 | PR | 140 |
| 125 | 3040 | MVN | Arbroth Levee Enlargement | 253 | R | 4405000525 | 4404000534 | Overtopping | 8593 | 1.152E-04 | 43.07 | 47.377 | 4.96E+03 | 5.46E+03 | 212 | MR | 25 |
| 134 | 3340 | MVN | Pt Coupee Levee Enlargement | 268 | R | 4405000525 | 4404000534 | Overtopping | 8593 | 1.152E-04 | 43.07 | 47.377 | 4.96E+03 | 5.46E+03 | 212 | MR | 25 |
| 316 | 2030 | MVK | Avon, Ms, Levee and Berms, Item 526.0+L | 526 | L | 5905000021 | 5904000034 | Seepage | 4876 | 4.911E-05 | 109.48 | 109.48 | 5.38E+03 | 5.38E+03 | 214 | UC | 33 |
| 348 | 2415 | MVK | Catfish Point, MS, Seepage Control, Item 572+L | 572 | L | 5905000021 | 5904000034 | Seepage | 4876 | 4.911E-05 | 109.48 | 109.48 | 5.38E+03 | 5.38E+03 | 214 | UC | 33 |
| 350 | 2425 | MVK | Eutaw+Mounds, Ms, Seepage Control, Item 563+L | 563 | L | 5905000021 | 5904000034 | Seepage | 4876 | 4.911E-05 | 109.48 | 109.48 | 5.38E+03 | 5.38E+03 | 214 | UC | 33 |
| 283 | 2080 | MVK | Cypress Creek, Ar, Seepage Control, Item 576+R | 576 | R | 5905000001 | 5904000062 | Seepage | 1400 | 3.518E-05 | 152.8 | 152.8 | 5.37E+03 | 5.37E+03 | 217 | UC | 36 |
| 284 | 2090 | MVK | Dewey, Ar, Seepage Control, Item 548+R | 548 | R | 5905000001 | 5904000062 | Seepage | 1400 | 3.518E-05 | 152.8 | 152.8 | 5.37E+03 | 5.37E+03 | 217 | UC | 36 |
| 290 | 2150 | MVK | Panther Forrest, Ar, Seepage Control, Item 543+R | 543 | R | 5905000001 | 5904000062 | Seepage | 1400 | 3.518E-05 | 152.8 | 152.8 | 5.37E+03 | 5.37E+03 | 217 | UC | 36 |
| 291 | 2220 | MVK | Sunnyside, Ar,, Levee and Berms, Item 531+R | 531 | R | 5905000001 | 5904000062 | Seepage | 1400 | 3.518E-05 | 152.8 | 152.8 | 5.37E+03 | 5.37E+03 | 217 | UC | 36 |
| 301 | 2335 | MVK | Yellow Bend, Ark, Seepage Control, Item 551+R | 551 | R | 5905000001 | 5904000062 | Seepage | 1400 | 3.518E-05 | 152.8 | 152.8 | 5.37E+03 | 5.37E+03 | 217 | UC | 36 |
| 304 | 2350 | MVK | Tarpley Island, Ark, Seepage Control, Item 542+R | 542 | R | 5905000001 | 5904000062 | Seepage | 1400 | 3.518E-05 | 152.8 | 152.8 | 5.37E+03 | 5.37E+03 | 217 | UC | 36 |
| 305 | 2355 | MVK | Vaucluse Bendway, Ark, Seepage Control, Item 53 | 533 | R | 5905000001 | 5904000062 | Seepage | 1400 | 3.518E-05 | 152.8 | 152.8 | 5.37E+03 | 5.37E+03 | 217 | UC | 36 |
| 139 | 3530 | MVN | ABLD+1 180 R | 180 | R | 4405000525 | 4404000534 | Overtopping | 8800 | 1.125E-04 | 43.07 | 47.377 | 4.84E+03 | 5.33E+03 | 224 | MR | 27 |
| 185 | 3565 | MVN | Item M+91.2+L; Arabi Levee Setback and Floodwa | 91 | L | 4405000556 | 4404000508 | Floodwall Stability | 2014 | 4.286E-05 | 112 | 123.2 | 4.80E+03 | 5.28E+03 | 225 | UC | 43 |

| | | | | | | | | | | Annual Probability | Consequence Data | | Risk Indexes | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| row number | Project Number | District | (7) Project Name | Project Center River Mile | Bank (L/R) | NLD System Number | NDL Segment Number | Failure Mode Addressed | Calculated OT Frequency | Annual Likelihood of Breach due to Failure Mode Addressed | LOL by Failure Mode | Adjusted LOL by Failure Mode | Risk Index | Adjusted Risk Index | Risk Rank | Item Catogory | Catagory Rank |
| 128 | 3160 | MVN | Fancy Point | 242.5 | R | 4405000525 | 4404000534 | Overtopping | 8141 | 1.216E-04 | 43.07 | 43.07 | 5.24E-03 | 5.24E-03 | 226 | MR | 28 |
| 227 | 2160 | MVK | Point Pleasant-Yucatan, La, Levee and Berms, Ite | 409 | R | 5905000001 | 5904000024 | Seepage | 1400 | 3.518E-05 | 147.04 | 147.04 | 5.17E-03 | 5.17E-03 | 227 | UC | 44 |
| 268 | 2555 | MVK | Moreville-Black Hawk, La, Seepage Control, Item | 348 | R | 5905000001 | 5904000024 | Seepage | 1400 | 3.518E-05 | 147.04 | 147.04 | 5.17E-03 | 5.17E-03 | 227 | UC | 44 |
| 272 | 2567 | MVK | Moreville-Black Hawk, La, Seepage Control, Item | 350 | R | 5905000001 | 5904000024 | Seepage | 1400 | 3.518E-05 | 147.04 | 147.04 | 5.17E-03 | 5.17E-03 | 227 | UC | 44 |
| 274 | 2575 | MVK | Moreville-Black Hawk, La, Seepage Control, Item | 352 | R | 5905000001 | 5904000024 | Seepage | 1400 | 3.518E-05 | 147.04 | 147.04 | 5.17E-03 | 5.17E-03 | 227 | UC | 44 |
| 318 | 2055 | MVK | Below Catfish Point,Ms, Seepage Control, Item 57 | 570 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 325 | 2075 | MVK | Catfish Point, Ms, Seepage Control, Item 571-L | 571 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 331 | 2175 | MVK | Riverton, Ms, Seepage Control, Item 585-L | 585 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 332 | 2180 | MVK | Rosedale, Ms, Seepage Control, Item 589-L | 589 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 334 | 2190 | MVK | Sledge-Waxhow, Ms, Seepage Control, Item 607- | 607 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 339 | 2370 | MVK | Smith Point, MS, Seepage Control, Item 601-L | 601 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 340 | 2375 | MVK | Victoria Bend, MS, Seepage Control, Item 594-L | 594 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 341 | 2380 | MVK | Above Rosedale, Ms, Seepage Control, Item 591- | 591 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 343 | 2390 | MVK | Rosedale Harbor, MS, Seepage Control, Item 584 | 584 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 344 | 2395 | MVK | Monterey Bend, MS, Seepage Control, Item 579-L | 579 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 345 | 2400 | MVK | Monterey Bend, MS, Seepage Control, Item 578-L | 578 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 347 | 2410 | MVK | Bolivar, Ms, Seepage Control, Item 575-L | 575 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 355 | 2450 | MVK | Lake Ferguson, Ms, Seepage Control, Item 541-L | 541 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 360 | 2475 | MVK | Avon, Ms, Seepage Control, Item 525-L | 525 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 361 | 2480 | MVK | Kentucky Bend, Ms, Seepage Control, Item 518-L | 518 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 362 | 2485 | MVK | Kentucky Bend, Ms, Seepage Control, Item 516-L | 516 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 120.428 | 3.84E-03 | 4.23E-03 | 231 | UC | 48 |
| 194 | 3155 | MVN | English Turn | 77 | R | 4405000557 | 4404000515 | Slope/Bank Stability | 4558 | 9.119E-04 | 4 | 4.4 | 3.65E-03 | 4.01E-03 | 247 | RV | 14 |
| 19 | 1590 | MVM | Drinkwater Pump Station | 23 M | R | 4005000002 | 4004000008 | Seepage | 500 | 4.955E-05 | 80 | 80 | 3.96E-03 | 3.96E-03 | 248 | UC | 64 |
| 326 | 2085 | MVK | Deerfield, Ms, Seepage Control, Item 531.5L-A | 531 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 109.48 | 3.84E-03 | 3.84E-03 | 249 | UC | 65 |
| 328 | 2100 | MVK | James-Longwood, Ms, Levee and Berms, Item 52 | 521 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 109.48 | 3.84E-03 | 3.84E-03 | 249 | UC | 65 |
| 330 | 2115 | MVK | Magna Vista-Brunswick, Ms, Levees and Berms, I | 462 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 109.48 | 3.84E-03 | 3.84E-03 | 249 | UC | 65 |
| 349 | 2420 | MVK | Eutaw-Mounds, Ms, Seepage Control, Item 565-L | 565 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 109.48 | 3.84E-03 | 3.84E-03 | 249 | UC | 65 |
| 351 | 2430 | MVK | Eutaw-Mounds, Ms, Seepage Control, Item 561-L | 561 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 109.48 | 3.84E-03 | 3.84E-03 | 249 | UC | 65 |
| 352 | 2435 | MVK | Huntington Point, MS, Seepage Control, Item 557 | 557 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 109.48 | 3.84E-03 | 3.84E-03 | 249 | UC | 65 |
| 353 | 2440 | MVK | Ashbrook-Miller Bend, Ms, Seepage Control, Item | 547 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 109.48 | 3.84E-03 | 3.84E-03 | 249 | UC | 65 |
| 354 | 2445 | MVK | Ashbrook-Miller Bend, Ms, Seepage Control, Item | 545 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 109.48 | 3.84E-03 | 3.84E-03 | 249 | UC | 65 |
| 357 | 2460 | MVK | Warfield, Ms, Seepage Control, Item 537-L | 537 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 109.48 | 3.84E-03 | 3.84E-03 | 249 | UC | 65 |
| 358 | 2465 | MVK | Lake Lee, Ms, Seepage Control, Item 527-L | 527 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 109.48 | 3.84E-03 | 3.84E-03 | 249 | UC | 65 |
| 359 | 2470 | MVK | Lake Lee, Ms, Seepage Control, Item 526.5-L | 526.5 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 109.48 | 3.84E-03 | 3.84E-03 | 249 | UC | 65 |
| 363 | 2490 | MVK | Island 82, Ms, Seepage Control, Item 534-L | 534 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 109.48 | 3.84E-03 | 3.84E-03 | 249 | UC | 65 |
| 365 | 2500 | MVK | Deeson, Ms, Seepage Control, Item 613-L | 613 | L | 5905000021 | 5904000034 | Seepage | 4876 | 3.509E-05 | 109.48 | 109.48 | 3.84E-03 | 3.84E-03 | 249 | UC | 65 |
| 55 | 1115 | MVM | Helena, AR Floodwall Replacement | 663 | R | 4005000006 | 4004000019 | Floodwall Stability | 8500 | 2.050E-04 | 15 | 16.5 | 3.07E-03 | 3.38E-03 | 262 | PR | 141 |
| 195 | 3280 | MVN | Oak Point Revetment | 72.5 | R | 4405000557 | 4404000515 | Slope/Bank Stability | 4558 | 7.468E-04 | 4 | 4.4 | 2.99E-03 | 3.29E-03 | 263 | RV | 15 |
| 293 | 2270 | MVK | Lake Chicot Pumping Plant Floodwall Phase III | 514 | R | 5905000001 | 5904000062 | Floodwall Stability | 1400 | 2.007E-05 | 152.8 | 152.8 | 3.07E-03 | 3.07E-03 | 264 | UC | 78 |
| 144 | 3370 | MVN | St Alice Revetment | 165.5 | R | 4405000526 | 4404000535 | Slope/Bank Stability | 6062 | 1.077E-03 | 2.36 | 2.596 | 2.54E-03 | 2.79E-03 | 265 | RV | 16 |
| 186 | 3620 | MVN | Chalmette Battle Field -wall Reach 1 | 90 | L | 4405000556 | 4404000508 | Floodwall Stability | 2014 | 2.195E-05 | 112 | 123.2 | 2.46E-03 | 2.70E-03 | 266 | UC | 79 |
| 98 | 3500 | MVN | Romeville/College Point 156.8 L | 156.8 | L | 4405000501 | 4404000502 | Overtopping | 5950 | 1.673E-04 | 16 | 16 | 2.68E-03 | 2.68E-03 | 267 | PR | 142 |
| 81 | 3000 | MVN | 35 Mile Point | 130 | L | 4405000501 | 4404000502 | Overtopping | 7060 | 1.410E-04 | 16 | 17.6 | 2.26E-03 | 2.48E-03 | 268 | PR | 143 |
| 118 | 3420 | MVN | Upper 5th | 317 | R | 4405000515 | 4404000520 | Overtopping | 3749 | 2.667E-04 | 9 | 9 | 2.40E-03 | 2.40E-03 | 269 | PR | 144 |
| 150 | 3460 | MVN | Waterford | 128.5 | R | 4405000526 | 4404000535 | Slope/Bank Stability | 6062 | 9.118E-04 | 2.36 | 2.596 | 2.15E-03 | 2.37E-03 | 270 | RV | 17 |

| | | | | | | | | | Annual Probability | Consequence Data | | Risk Indexes | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| row number | Project Number | District | (7) Project Name | Project Center River Mile | Bank (L/R) | NLD System Number | NDL Segment Number | Failure Mode Addressed | Calculated OT Frequency | Annual Likelihood of Breach due to Failure Mode Addressed | LOL by Failure Mode | Adjusted LOL by Failure Mode | Risk Index | Adjusted Risk Index | Risk Rank | Item Catogory | Catagory Rank |
| 88 | 3240 | MVN | Lower Plaquemines Point | 199 | L | 4405000501 | 4404000502 | Overtopping | 7500 | 1.327E-04 | 16 | 17.6 | 2.12E+03 | 2.34E+03 | 271 | PR | 145 |
| 92 | 3295 | MVN | Paulina/Lutcher/Gramercy | 148 | L | 4405000501 | 4404000502 | Overtopping | 7750 | 1.285E-04 | 16 | 17.6 | 2.06E+03 | 2.26E+03 | 272 | PR | 146 |
| 85 | 3105 | MVN | Carville | 189 | L | 4405000501 | 4404000502 | Overtopping | 7982 | 1.247E-04 | 16 | 17.6 | 2.00E+03 | 2.20E+03 | 273 | PR | 147 |
| 142 | 3245 | MVN | Lucy Revetment | 135.5 | R | 4405000526 | 4404000535 | Slope/Bank Stability | 6062 | 8.293E-04 | 2.36 | 2.596 | 1.96E+03 | 2.15E+03 | 274 | RV | 18 |
| 86 | 3180 | MVN | Gramercy.Mt. Airy/48 mile Point | 144 | L | 4405000501 | 4404000502 | Overtopping | 8150 | 1.221E-04 | 16 | 17.6 | 1.95E+03 | 2.15E+03 | 275 | MR | 29 |
| 217 | 3645 | MVN | Marerro | 0 | 0 | 4405000557 | 4404000558 | Floodwall Stability | 4558 | 2.550E-06 | 750 | 825 | 1.91E+03 | 2.10E+03 | 276 | UC | 80 |
| 94 | 3345 | MVN | Reserve | 136 | L | 4405000501 | 4404000502 | Overtopping | 8363 | 1.190E-04 | 16 | 17.6 | 1.90E+03 | 2.10E+03 | 277 | MR | 30 |
| 97 | 3465 | MVN | Welham  Plantation | 154 | L | 4405000501 | 4404000502 | Overtopping | 8474 | 1.175E-04 | 16 | 17.6 | 1.88E+03 | 2.07E+03 | 278 | MR | 31 |
| 87 | 3235 | MVN | Laplace | 133 | L | 4405000501 | 4404000502 | Overtopping | 8500 | 1.171E-04 | 16 | 17.6 | 1.87E+03 | 2.06E+03 | 279 | MR | 32 |
| 53 | 1610 | MVM | Hickman, KY Floodwall and Levee | 922 | L | 4005000003 | 4004000060 | Seepage | 2125 | 4.918E-05 | 38 | 41.8 | 1.87E+03 | 2.06E+03 | 280 | UC | 81 |
| 50 | 1125 | MVM | Hickman Floodwall Embankment Tie-in | 922 | L | 4005000003 | 4004000060 | Overtopping | 2125 | 4.652E-04 | 4 | 4.4 | 1.86E+03 | 2.05E+03 | 281 | PR | 148 |
| 84 | 3090 | MVN | Burnside | 168 | L | 4405000501 | 4404000502 | Overtopping | 8615 | 1.156E-04 | 16 | 17.6 | 1.85E+03 | 2.03E+03 | 282 | MR | 33 |
| 82 | 3070 | MVN | Belmont | 152 | L | 4405000501 | 4404000502 | Overtopping | 8892 | 1.120E-04 | 16 | 17.6 | 1.79E+03 | 1.97E+03 | 283 | MR | 34 |
| 83 | 3075 | MVN | Ben Hur Road | 217.6 | L | 4405000501 | 4404000502 | Overtopping | 8235 | 1.209E-04 | 16 | 16 | 1.93E+03 | 1.93E+03 | 284 | MR | 35 |
| 95 | 3350 | MVN | Romeville | 163 | L | 4405000501 | 4404000502 | Overtopping | 9126 | 1.091E-04 | 16 | 17.6 | 1.75E+03 | 1.92E+03 | 285 | MR | 36 |
| 179 | 3205 | MVN | Holy Cross | 92 | L | 4405000556 | 4404000507 | Overtopping | 7391 | 1.331E-04 | 13 | 14.3 | 1.73E+03 | 1.90E+03 | 286 | PR | 149 |
| 89 | 3250 | MVN | Marchand | 181 | L | 4405000501 | 4404000502 | Overtopping | 9274 | 1.073E-04 | 16 | 17.6 | 1.72E+03 | 1.89E+03 | 287 | MR | 37 |
| 180 | 3110 | MVN | Chalmette Battle Field (1) | 88.5 | L | 4405000556 | 4404000508 | Overtopping | 7521 | 1.308E-04 | 13 | 14.3 | 1.70E+03 | 1.87E+03 | 288 | PR | 150 |
| 182 | 3115 | MVN | Chalmette Slip | 90 | L | 4405000556 | 4404000508 | Overtopping | 7591 | 1.296E-04 | 13 | 14.3 | 1.68E+03 | 1.85E+03 | 289 | PR | 151 |
| 47 | 1320 | MVM | Ridgley, TN Item 863 | 863 | L | 4005000003 | 4004000013 | Seepage | 2125 | 4.546E-05 | 36 | 39.6 | 1.64E+03 | 1.80E+03 | 290 | UC | 82 |
| 366 | 2265 | MVK | Vicksburg FW Phase III | 437 | L | 5905000032 | 5904000035 | Floodwall Stability | 10000 | 1.994E-04 | 8 | 8.8 | 1.60E+03 | 1.75E+03 | 291 | PR | 152 |
| 181 | 3111 | MVN | Chalmette Battle Field (2) | 86.1 | L | 4405000556 | 4404000508 | Overtopping | 8227 | 1.195E-04 | 13 | 14.3 | 1.55E+03 | 1.71E+03 | 292 | MR | 38 |
| 111 | 3085 | MVN | Buras Revetment | 25.1 | R | 4405000512 | 4404000517 | Slope/Bank Stability | 9407 | 6.459E-04 | 2 | 2.2 | 1.29E+03 | 1.42E+03 | 293 | RV | 19 |
| 40 | 1480 | MVM | Pecan Point, AR Slope Flattening (116/40+00 to 1 | 762 | R | 4005000002 | 4004000017 | Slope/Bank Stability | 500 | 6.073E-06 | 229 | 229 | 1.39E+03 | 1.39E+03 | 294 | MR | 39 |
| 41 | 1490 | MVM | Wilson, AR Slope Flattening (100/00+00 to 100/3 | 766 | R | 4005000002 | 4004000017 | Slope/Bank Stability | 500 | 6.073E-06 | 229 | 229 | 1.39E+03 | 1.39E+03 | 294 | MR | 39 |
| 42 | 1500 | MVM | Barfield, AR Slope Flattening (61/00+00 to 61/25- | 807 | R | 4005000002 | 4004000017 | Slope/Bank Stability | 500 | 6.073E-06 | 229 | 229 | 1.39E+03 | 1.39E+03 | 294 | MR | 39 |
| 119 | 3485 | MVN | Combined Lower/Upper 5th 308-317W | 312.5 | R | 4405000515 | 4404000520 | Overtopping | 7000 | 1.429E-04 | 9 | 9 | 1.29E+03 | 1.29E+03 | 297 | PR | 153 |
| 66 | 1670 | MVM | Elaine, AR to Laconia Circle Levee (48/4+00S to 4 | 620 | R | 4005000006 | 4004000021 | Overtopping | 8500 | 1.152E-04 | 9 | 9.9 | 1.04E+03 | 1.14E+03 | 298 | MR | 42 |
| 60 | 1420 | MVM | Williamson, AR | 657 | R | 4005000006 | 4004000020 | Seepage | 8500 | 6.929E-05 | 15 | 15 | 1.04E+03 | 1.04E+03 | 299 | UC | 83 |
| 5 | 1470 | MVM | Mound City Floodwall | 961 | R | 4005000001 | 4004000001 | Floodwall Stability | 300 | 2.033E-05 | 51 | 51 | 1.04E+03 | 1.04E+03 | 300 | UC | 84 |
| 61 | 1030 | MVM | Above Ferguson, AR | 623 | R | 4005000006 | 4004000021 | Seepage | 8500 | 6.929E-05 | 14 | 14 | 9.70E+04 | 9.70E+04 | 301 | UC | 85 |
| 11 | 1045 | MVM | Cairo, IL Slope Flattening | 957 | L | 4005000001 | 4004000005 | Slope/Bank Stability | 300 | 6.090E-06 | 147 | 147 | 8.95E+04 | 8.95E+04 | 302 | MR | 43 |
| 52 | 1570 | MVM | Hickman Levee Grade Raise | 922 | L | 4005000003 | 4004000060 | Overtopping | 5312 | 1.861E-04 | 4 | 4.4 | 7.44E+04 | 8.19E+04 | 303 | PR | 154 |
| 65 | 1160 | MVM | Henrico, AR 606 R | 606 | R | 4005000006 | 4004000023 | Seepage | 8500 | 5.775E-05 | 14 | 14 | 8.09E+04 | 8.09E+04 | 304 | UC | 86 |
| 56 | 1150 | MVM | Helena, AR | 663 | R | 4005000006 | 4004000019 | Seepage | 8500 | 4.538E-05 | 15 | 16.5 | 6.81E+04 | 7.49E+04 | 305 | UC | 87 |
| 76 | 1260 | MVM | Nash #2 | 957 | R | 4005000021 | 4004000057 | Seepage | 10000 | 4.043E-05 | 12 | 13.2 | 4.85E+04 | 5.34E+04 | 306 | UC | 88 |
| 193 | 3395 | MVN | Stanton | 84.3 | R | 4405000557 | 4404000514 | Overtopping | 8171 | 1.204E-04 | 4 | 4.4 | 4.81E+04 | 5.30E+04 | 307 | MR | 44 |
| 46 | 1560 | MVM | Lake No. 9 - KY-TN State Line (21/3+80 to 21/7+3 | 902 | L | 4005000003 | 4004000012 | Overtopping | 7880 | 1.255E-04 | 4 | 4 | 5.02E+04 | 5.02E+04 | 308 | PR | 155 |
| 106 | 3140 | MVN | Diamond | 48 | R | 4405000511 | 4404000516 | Slope/Bank Stability | 5200 | 4.976E-04 | 1 | 1 | 4.98E+04 | 4.98E+04 | 309 | RV | 20 |
| 146 | 3385 | MVN | St. James Moonshine | 156 | R | 4405000526 | 4404000535 | Overtopping | 6062 | 1.639E-04 | 2.36 | 2.36 | 3.87E+04 | 3.87E+04 | 310 | PR | 156 |
| 140 | 3005 | MVN | Aben | 172.6 | R | 4405000526 | 4404000535 | Overtopping | 6906 | 1.439E-04 | 2.36 | 2.596 | 3.40E+04 | 3.73E+04 | 311 | PR | 157 |
| 151 | 3490 | MVN | Brilliant Point 163.5 R (Note: Item #3480 Welcom | 163.5 | R | 4405000526 | 4404000535 | Overtopping | 7000 | 1.419E-04 | 2.36 | 2.596 | 3.35E+04 | 3.68E+04 | 312 | PR | 158 |
| 143 | 3315 | MVN | Point Houmas (Lauderdale) | 165 | R | 4405000526 | 4404000535 | Overtopping | 7187 | 1.382E-04 | 2.36 | 2.596 | 3.26E+04 | 3.59E+04 | 313 | PR | 159 |
| 155 | 3510 | MVN | Hahnville, Flagville, Dufresne 120-128.5 R | 124.3 | R | 4405000526 | 4404000535 | Overtopping | 6693 | 1.484E-04 | 2.36 | 2.36 | 3.50E+04 | 3.50E+04 | 314 | PR | 160 |
| 156 | 3520 | MVN | Oak Alley - Willow Grove 142.6-144 R | 143.7 | L | 4405000526 | 4404000535 | Overtopping | 7750 | 1.282E-04 | 2.36 | 2.596 | 3.03E+04 | 3.33E+04 | 315 | PR | 161 |

| | | | | | | | | | Annual Probability | Consequence Data | | Risk Indexes | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| row number | Project Number | District | (7) Project Name | Project Center River Mile | Bank (L/R) | NLD System Number | NDL Segment Number | Failure Mode Addressed | Calculated OT Frequency | Annual Likelihood of Breach due to Failure Mode Addressed | LOL by Failure Mode | Adjusted LOL by Failure Mode | Risk Index | Adjusted Risk Index | Risk Rank | Item Catogory | Catagory Rank |
| 120 | 3360 | MVN | Smithland to Lacour289ד298 R | 293.5 | R | 4405000523 | 4404000530 | Overtopping | 2625 | 3.711E-04 | 0.8 | 0.88 | 2.97E-04 | 3.27E-04 | 316 | PR | 162 |
| 153 | 3496 | MVN | Lower Edgard 131.7 R | 131.7 | R | 4405000526 | 4404000535 | Overtopping | 7300 | 1.361E-04 | 2.36 | 2.36 | 3.21E-04 | 3.21E-04 | 317 | PR | 163 |
| 69 | 1000 | MVM | Above Dorena, P-1, MO 929 R | 918 | R | 4005000016 | 4004000076 | Seepage | 100 | 2.915E-04 | 1 | 1.1 | 2.91E-04 | 3.21E-04 | 318 | UC | 89 |
| 71 | 1010 | MVM | Above Dorena, P-2, MO 929 R | 925 | R | 4005000016 | 4004000076 | Seepage | 100 | 2.915E-04 | 1 | 1.1 | 2.91E-04 | 3.21E-04 | 318 | UC | 89 |
| 72 | 1020 | MVM | Above Dorena, P-3, MO 929 R | 934 | R | 4005000016 | 4004000076 | Seepage | 100 | 2.915E-04 | 1 | 1.1 | 2.91E-04 | 3.21E-04 | 318 | UC | 89 |
| 73 | 1060 | MVM | Bayouville, MO 913R | 914 | R | 4005000016 | 4004000076 | Seepage | 100 | 2.915E-04 | 1 | 1.1 | 2.91E-04 | 3.21E-04 | 318 | UC | 89 |
| 74 | 1180 | MVM | Hubbard Lake, MO Item 892R | 908 | R | 4005000016 | 4004000076 | Seepage | 100 | 2.915E-04 | 1 | 1.1 | 2.91E-04 | 3.21E-04 | 318 | UC | 89 |
| 147 | 3400 | MVN | Stella Landing | 173.9 | R | 4405000526 | 4404000535 | Overtopping | 8474 | 1.172E-04 | 2.36 | 2.596 | 2.77E-04 | 3.04E-04 | 323 | MR | 45 |
| 145 | 3375 | MVN | St. Amelia 158R | 158 | R | 4405000526 | 4404000535 | Overtopping | 8593 | 1.156E-04 | 2.36 | 2.596 | 2.73E-04 | 3.00E-04 | 324 | MR | 46 |
| 149 | 3455 | MVN | Wallace | 147.3 | R | 4405000526 | 4404000535 | Overtopping | 8695 | 1.143E-04 | 2.36 | 2.596 | 2.70E-04 | 2.97E-04 | 325 | MR | 47 |
| 152 | 3495 | MVN | Upper Edgard 142 R | 142 | R | 4405000526 | 4404000535 | Overtopping | 8000 | 1.242E-04 | 2.36 | 2.36 | 2.93E-04 | 2.93E-04 | 326 | MR | 48 |
| 100 | 3095 | MVN | Carnaevon to Phoenix | 67 | L | 4405000506 | 4404000509 | Slope/Bank Stability | 7344 | 6.459E-04 | 0.4 | 0.44 | 2.58E-04 | 2.84E-04 | 327 | RV | 21 |
| 141 | 3230 | MVN | Lone Star to Davis Pond | 119.2 | R | 4405000526 | 4404000535 | Overtopping | 9121 | 1.089E-04 | 2.36 | 2.596 | 2.57E-04 | 2.83E-04 | 328 | MR | 49 |
| 154 | 3497 | MVN | Lower Edgard (3) 135.2ד136.2 R | 135.7 | R | 4405000526 | 4404000535 | Overtopping | 8346 | 1.190E-04 | 2.36 | 2.36 | 2.81E-04 | 2.81E-04 | 329 | MR | 50 |
| 188 | 3630 | MVN | Item Mד90.8ךL; Amstar Levee Setback Enlargeme | 91 | L | 4405000556 | 4404000508 | Floodwall Stability | 2014 | 2.152E-06 | 112 | 123.2 | 2.41E-04 | 2.65E-04 | 330 | UC | 94 |
| 148 | 3435 | MVN | Vacherie | 149 | R | 4405000526 | 4404000535 | Overtopping | 9731 | 1.021E-04 | 2.36 | 2.596 | 2.41E-04 | 2.65E-04 | 331 | MR | 51 |
| 210 | 3275 | MVN | Nine Mile Point ד Landside shift | 105.5 | R | 4405000557 | 4404000558 | Slope/Bank Stability | 4558 | 2.770E-03 | 322 | 354.2 | 8.92E-01 | 9.81E-01 | 10 | PR | 9 |
| 198 | 3045 | MVN | Avondale Revetment (Awarded) | 108.5 | R | 4405000557 | 4404000558 | Slope/Bank Stability | 4558 | 2.770E-03 | 322 | 354.2 | 8.92E-01 | 9.81E-01 | 10 | RV | 2 |
| 175 | 3600 | MVN | Spanish Plaza | 95 | L | 4405000556 | 4404000505 | Floodwall Stability | 2014 | 2.002E-04 | 4121 | 4533.1 | 8.25E-01 | 9.07E-01 | 12 | PR | 10 |
| 161 | 3225 | MVN | Kenner Bend Revetment | 115 | L | 4405000556 | 4404000503 | Slope/Bank Stability | 2014 | 7.470E-04 | 974 | 1071.4 | 7.28E-01 | 8.00E-01 | 13 | RV | 3 |
| 9 | 1035 | MVM | Cairo, IL Floodwall | 957 | R | 4005000001 | 4004000003 | Floodwall Stability | 300 | 5.379E-03 | 147 | 147 | 7.91E-01 | 7.91E-01 | 14 | PR | 11 |
| 307 | 1110 | MVM | Commerce, MS | 698 | L | 5905000021 | 4004000026 | Seepage | 4876 | 4.829E-03 | 117 | 117 | 5.65E-01 | 5.65E-01 | 15 | PR | 12 |
| 310 | 1270 | MVM | Norfolk, MS | 712 | L | 5905000021 | 4004000026 | Seepage | 4876 | 4.829E-03 | 117 | 117 | 5.65E-01 | 5.65E-01 | 15 | PR | 12 |
| 164 | 3210 | MVN | INHC Lock ד Structure | 93 | L | 4405000556 | 4404000505 | Overtopping | 2014 | 4.883E-04 | 974 | 1071.4 | 4.76E-01 | 5.23E-01 | 17 | LK | 1 |
| 33 | 1170 | MVM | Horseshoe Lake, AR | 705 | R | 4005000002 | 4004000017 | Seepage | 500 | 2.054E-03 | 229 | 229 | 4.70E-01 | 4.70E-01 | 18 | PR | 14 |
| 4 | 1430 | MVM | North Mound City, IL Sump | 961 | R | 4005000001 | 4004000001 | Seepage | 300 | 7.406E-03 | 51 | 51 | 3.78E-01 | 3.78E-01 | 19 | PR | 15 |
| 221 | 2040 | MVK | Bayou VidalדElkridge, La, Levee and Berms, Item 4 | 414 | R | 5905000001 | 5904000024 | Seepage | 1400 | 2.567E-03 | 147.04 | 147.04 | 3.77E-01 | 3.77E-01 | 20 | PR | 16 |
| 172 | 3585 | MVN | Item Mד100ךL; NASHVILLE AVE. TO NAPOLEON AV | 100 | L | 4405000556 | 4404000505 | Floodwall Stability | 2014 | 8.067E-05 | 4121 | 4533.1 | 3.32E-01 | 3.66E-01 | 21 | UC | 1 |
| 233 | 2200 | MVK | St. JosephדWaterproof, La, Levee and Berms, Iten | 385 | R | 5905000001 | 5904000024 | Seepage | 1400 | 2.190E-03 | 147.04 | 161.744 | 3.22E-01 | 3.54E-01 | 22 | PR | 17 |
| 203 | 3150 | MVN | Dugas to Celotex | 100.4 | R | 4405000557 | 4404000558 | Seepage | 4558 | 4.091E-04 | 750 | 825 | 3.07E-01 | 3.37E-01 | 23 | PR | 18 |
| 209 | 3275 | MVN | Nine Mile Point (Awarded) | 105.5 | R | 4405000557 | 4404000558 | Seepage | 4558 | 4.091E-04 | 750 | 825 | 3.07E-01 | 3.37E-01 | 23 | PR | 18 |
| 278 | 2015 | MVK | Above LakeportדHarwood, Ark, Levee and Berms, | 525 | R | 5905000001 | 5904000062 | Seepage | 1400 | 2.190E-03 | 152.79 | 152.79 | 3.35E-01 | 3.35E-01 | 25 | PR | 20 |
| 280 | 2020 | MVK | Above LakeportדHarwood, Ark, Levee and Berms, | 528 | R | 5905000001 | 5904000062 | Seepage | 1400 | 2.190E-03 | 152.79 | 152.79 | 3.35E-01 | 3.35E-01 | 25 | PR | 20 |
| 247 | 2255 | MVK | YucatanדLake Bruin, La, Levees and Berms, Item 3 | 398 | R | 5905000001 | 5904000024 | Seepage | 1400 | 2.028E-03 | 147.04 | 161.744 | 2.98E-01 | 3.28E-01 | 27 | PR | 22 |
| 160 | 3135 | MVN | Destrahan Revetment | 120 | L | 4405000556 | 4404000503 | Slope/Bank Stability | 2014 | 2.996E-04 | 974 | 1071.4 | 2.92E-01 | 3.21E-01 | 28 | RV | 4 |
| 166 | 3265 | MVN | New Orleans District (Awarded) | 102.7 | L | 4405000556 | 4404000505 | Overtopping | 3755 | 2.619E-04 | 974 | 1071.4 | 2.55E-01 | 2.81E-01 | 29 | PR | 23 |
| 276 | 2010 | MVK | Above LakeportדHarwood, Ark, Levee and Berms, | 520 | R | 5905000001 | 5904000062 | Seepage | 1400 | 1.574E-03 | 152.79 | 152.79 | 2.41E-01 | 2.41E-01 | 30 | PR | 24 |
| 235 | 2205 | MVK | St. JosephדWaterproof, La, Levee and Berms, Iten | 388 | R | 5905000001 | 5904000024 | Seepage | 1400 | 1.574E-03 | 147.04 | 147.04 | 2.31E-01 | 2.31E-01 | 31 | PR | 25 |
| ~~263~~ | ~~2535~~ | ~~MVK~~ | ~~MorevilleדBlack Hawk, La, Seepage Control, Item~~ | ~~340~~ | ~~R~~ | ~~5905000001~~ | ~~5904000024~~ | ~~Seepage~~ | ~~1400~~ | ~~1.574E-03~~ | ~~147.04~~ | ~~147.04~~ | ~~2.31E-01~~ | ~~2.31E-01~~ | ~~31~~ | ~~PR~~ | ~~25~~ |
| 266 | 2545 | MVK | MorevilleדBlack Hawk, La, Seepage Control, Item | 345 | R | 5905000001 | 5904000024 | Seepage | 1400 | 1.574E-03 | 147.04 | 147.04 | 2.31E-01 | 2.31E-01 | 31 | PR | 25 |
| 306 | 1100 | MVM | Clack, MS | 698 | L | 5905000021 | 4004000026 | Seepage | 4876 | 1.954E-03 | 117 | 117 | 2.29E-01 | 2.29E-01 | 34 | PR | 28 |
| 311 | 1340 | MVM | Sherard, MS | 629 | L | 5905000021 | 4004000026 | Seepage | 4876 | 1.954E-03 | 117 | 117 | 2.29E-01 | 2.29E-01 | 34 | PR | 28 |
| ~~313~~ | ~~1380~~ | ~~MVM~~ | ~~Walls, MS~~ | ~~712~~ | ~~L~~ | ~~5905000021~~ | ~~4004000026~~ | ~~Seepage~~ | ~~4876~~ | ~~1.954E-03~~ | ~~117~~ | ~~117~~ | ~~2.29E-01~~ | ~~2.29E-01~~ | ~~34~~ | ~~PR~~ | ~~28~~ |
| 177 | 3610 | MVN | Item Mד94.3 to 93.9ךL; BARRACKS ST. TO MONTE | 0 | 0 | 4405000556 | 4404000505 | Floodwall Stability | 2014 | 5.004E-05 | 4121 | 4533.1 | 2.06E-01 | 2.27E-01 | 37 | UC | 2 |
| 178 | 3615 | MVN | Item Mד93.9 to 93.3ךL; MONTEGUT ST. TO INDEP | 0 | 0 | 4405000556 | 4404000505 | Floodwall Stability | 2014 | 5.004E-05 | 4121 | 4533.1 | 2.06E-01 | 2.27E-01 | 37 | UC | 2 |

| | | | | | | | | | | Annual Probability | Consequence Data | | Risk Indexes | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| row number | Project Number | District | (7) Project Name | Project Center River Mile | Bank (L/R) | NLD System Number | NDL Segment Number | Failure Mode Addressed | Calculated OT Frequency | Annual Likelihood of Breach due to Failure Mode Addressed | LOL by Failure Mode | Adjusted LOL by Failure Mode | Risk Index | Adjusted Risk Index | Risk Rank | Item Catogory | Catagory Rank |
| 122 | 3360 | MVN | Smithland to Lacour289π298 R | 293.5 | R | 4405000523 | 4404000530 | Slope/Bank Stability | 2625 | 3.718Eπ05 | 0.8 | 0.88 | 2.97Eπ05 | 3.27Eπ05 | 363 | RV | 29 |
| 114 | 3335 | MVN | Port Sulphur | 37 | R | 4405000512 | 4404000517 | Overtopping | 9407 | 1.056Eπ04 | 0.22 | 0.242 | 2.32Eπ05 | 2.56Eπ05 | 364 | MR | 59 |
| 17 | 1325 | MVM | Setback Levee Slope Flattening | 942 | R | 4005000002 | 4004000008 | Slope/Bank Stability | 500 | 1.452Eπ07 | 80 | 80 | 1.16Eπ05 | 1.16Eπ05 | 365 | MR | 60 |
| 75 | 1650 | MVM | Birds Point π New Madrid Frontline Levee (43/21+ | 920 | R | 4005000016 | 4004000076 | Overtopping | 500 | 1.999Eπ03 | 0 | 0 | 0.00E+00 | 0.00E+00 | 366 | MR | 61 |